

TABLE 2. — Correction factor F_2 —Continued $s/r = 0.620$

	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.44184	2.44170	2.44130	2.44062	2.43967	2.43846	2.43697	2.43522	2.43319	2.43090
0.1	2.42834	2.42551	2.42241	2.41905	2.41543	2.41154	2.40739	2.40297	2.39830	2.39337
0.2	2.38818	2.38274	2.37705	2.37111	2.36492	2.35849	2.35182	2.34492	2.33778	2.33041
0.3	2.32282	2.31502	2.30700	2.29877	2.29035	2.28174	2.27294	0.	0.	0.

 $s/r = 0.630$

	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.40352	2.40339	2.40299	2.40232	2.40139	2.40020	2.39874	2.39702	2.39503	2.39278
0.1	2.39027	2.38749	2.38446	2.38116	2.37761	2.37380	2.36973	2.36541	2.36083	2.35601
0.2	2.35093	2.34561	2.34005	2.33425	2.32820	2.32193	2.31542	2.30869	2.30173	2.29456
0.3	2.28718	2.27959	2.27180	0.	0.	0.	0.	0.	0.	0.

 $s/r = 0.640$

	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.36557	2.36544	2.36505	2.36440	2.36349	2.36232	2.36089	2.35920	2.35725	2.35505
0.1	2.35258	2.34987	2.34689	2.34367	2.34019	2.33646	2.33248	2.32826	2.32378	2.31907
0.2	2.31411	2.30892	2.30349	2.29783	2.29194	2.28583	2.27949	2.27294	2.26618	0.

 $s/r = 0.650$

	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.32799	2.32786	2.32748	2.32684	2.32595	2.32481	2.32341	2.32175	2.31985	2.31769
0.1	2.31528	2.31263	2.30972	2.30657	2.30317	2.29953	2.29564	2.29152	2.28715	2.28256
0.2	2.27772	2.27266	2.26738	0.	0.	0.	0.	0.	0.	0.

 $s/r = 0.660$

	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.29078	2.29066	2.29028	2.28966	2.28879	2.28767	2.28630	2.28469	2.28283	2.28072
0.1	2.27837	2.27578	2.27294	2.26986	2.26655	0.	0.	0.	0.	0.