

TABLE 1.—Correction factor F_1 —Continued

$s/r = 0.550$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.72015	2.71983	2.71884	2.71720	2.71490	2.71193	2.70830	2.70398	2.69898	2.69327
0.1	2.68686	2.67973	2.67185	2.66322	2.65382	2.64362	2.63260	2.62073	0.	0.
$s/r = 0.560$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.67935	2.67901	2.67801	2.67633	2.67397	2.67093	2.66720	2.66278	2.65765	2.65181
0.1	2.64524	2.63793	2.62986	2.62101	2.61137	2.60091	2.58960	0.	0.	0.
$s/r = 0.570$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.63888	2.63854	2.63751	2.63579	2.63337	2.63026	2.62644	2.62191	2.61666	2.61068
0.1	2.60394	2.59645	2.58818	2.57911	2.56923	0.	0.	0.	0.	0.
$s/r = 0.580$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.59876	2.59841	2.59735	2.59559	2.59312	2.58993	2.58602	2.58139	2.57601	2.56988
0.1	2.56298	2.55530	2.54683	2.53754	0.	0.	0.	0.	0.	0.
$s/r = 0.590$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.55899	2.55863	2.55755	2.55574	2.55321	2.54995	2.54595	2.54120	2.53570	2.52942
0.1	2.52236	2.51449	0.	0.	0.	0.	0.	0.	0.	0.
$s/r = 0.600$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.51957	2.51921	2.51810	2.51625	2.51367	2.51033	2.50623	2.50137	2.49573	2.48931
0.1	2.48207	0.	0.	0.	0.	0.	0.	0.	0.	0.
$s/r = 0.610$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.48052	2.48015	2.47901	2.47713	2.47448	2.47106	2.46687	2.46189	2.45612	0.
$s/r = 0.620$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.44184	2.44145	2.44029	2.43836	2.43565	2.43215	2.42786	2.42277	0.	0.
$s/r = 0.630$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.40352	2.40312	2.40194	2.39996	2.39719	2.39361	0.	0.	0.	0.
$s/r = 0.640$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.36557	2.36517	2.36396	2.36193	2.35909	0.	0.	0.	0.	0.
$s/r = 0.650$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.32799	2.32758	2.32634	0.	0.	0.	0.	0.	0.	0.
$s/r = 0.660$										
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.	2.29078	2.29036	0.	0.	0.	0.	0.	0.	0.	0.